

Internal
8/035/0028



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program June 7, 2010

Reviewed: 

Mine Name: Donna Gibson	Permit Number: S/035/0028
Operator Name: Jared Stoddard	Inspection Date: October 27, 2009
Inspector(s): L Heppler	Time: 8:00 am
Other Participants: none	Mine Status: Active – Inspection requested

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$5,000 **Permit fee** is up to date (inspect status requested)

Purpose of Inspection: Operator requested inspection for bond release on 02/05/2009. This site was inspected as a small mine site on 03/13/2007

Inspection Summary: This has been recently mined. No photos taken.

Conclusions and Recommendations: After talking with numerous Operators it was determined that the permitted Operator had reclaimed, but a second Operator re-mined at the reclaimed site. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: Jared Stoddard

O:\M035-SaltLake\S0350028-DonnaGibson\inspections\Insp-10272009.doc





Recent regraded site



Recent regraded site



Recent regraded site



Recent regraded site w/ older regraded and vegetated site in the background